Material Safety Data Sheet

SULPHURIC ACID AR (RXSOL-60-6605-638)

1. Product and Company Identifaction

Product Name	RXSOL-60-6605-638
Product Type	SULPHURIC ACID AR
Revised date	

Company Details:

RX MARINE INTERNATIONAL
105, A wing , BSEL , TECH PARK.
VASHI ,NEW BOMBAY 400703 INDIA

Stock Point : Mumbai, Kandla, Chennai, Visakhapatnam, Kolkata, Fujairah, Muscat Barka

Phone	+91 22 27815541 / 42
Fax	+91 22 2781 1318 :::AOH :0091 9821214367
Email	mail@rxmarine.com

2. Composition / informationon ingredients

Substance / Preparation : Sulphuric acid
CAS No :7664-93-9
Substance.
Contains no other components or impurities which will influence the classification of the product.

3. Hazards Identification

3.1. Classification of the substance or mixture
Classification EC 67/548 or EC 1999/45
Classification : C; R35
Hazard Class and Category Code(s), Regulation (EC) No 1272/2008 (CLP)
Health hazards : Skin corrosion - Category 1A - Danger (CLP : Skin Corr. 1A) H314
Serious eye damage - Category 1 - Danger (CLP : Eye Dam. 1) H318
3.2. Label elements
Labelling EC 67/548 or EC 1999/45
Symbol(s) : C : Corrosive
R Phrase(s) : R35 : Causes severe burns.
S Phrase(s) : S1/2 : Keep locked up and out of reach of children.
S26 : In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.
S30 : Never add water to this product.
S45 : In case of accident or if you feel unwell, seek medical advice immediately (show the label when possible).
Labelling Regulation EC 1272/2008 (CLP)
Hazard pictograms

Signal words : Danger
Hazard statements : H314 : Causes severe skin burns and eye damage.
Precautionary statements
• General : P102: Keep out of reach of children.
P103: Read label before use.

P101: If medical advice is needed, have product container or label at hand.
• Prevention : P280: Wear protective gloves, protective clothing, eye protection, face protection.
P260: Do not breathe dust, fume, gas, mist, vapours, spray.
P264: Wash thoroughly after handling.
• Response : P301+P330+P331: IF SWALLOWED : Rinse mouth. Do NOT induce vomiting.
P305+P351+P338: IF IN EYES : Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
P303+P361+P353: IF ON SKIN (or hair) : Remove immediately all contaminated clothing. Rinse skin with water/shower.
P363: Wash contaminated clothing before reuse.
• Storage : P405: Store locked up.
• Disposal considerations : P501: Dispose of this material and its container to hazardous or special waste collection point, in accordance with local, regional, national and/or international regulation.
3.3. Other hazards
Other hazards : The substance does not fulfil the criteria to be identified as PBT substance or vPvB substance according to Annex XIII of Regulation REACH.

4. First Aid Measures

4.1. Description of first aid measures
Inhalation : Immediately call a POISON CENTER or doctor. Remove to fresh air and keep at rest in a position comfortable for breathing.
Skin contact : Wash with plenty of soap and water. Immediately call a POISON CENTER or doctor. Remove/Take off immediately all contaminated clothing.
Eye contact : Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor. Rinse cautiously with water for several minutes.
Ingestion : Rinse mouth. Immediately call a POISON CENTER or doctor. Do NOT induce vomiting.
4.2. Most important symptoms and effects, both acute and delayed
Symptoms relating to use : Causes severe skin burns and eye damage.
4.3. Indication of any immediate medical attention and special treatment needed
General information : Never give anything by mouth to an unconscious person. If you feel unwell, seek medical advice (show the label where possible).

5. Fire-fighting Measures

5.1. Extinguishing media
Suitable extinguishing media : Foam. Dry powder. Carbon dioxide. Water spray. Sand.
Unsuitable extinguishing media : Do not use a heavy water stream.
Surrounding fires : Use water spray or fog for cooling exposed containers.
5.2. Special hazards arising from the substance or mixture
Hazardous combustion products : Under fire conditions, hazardous fumes will be present. Thermal decomposition generates : Corrosive vapours.
5.3. Advice for fire-fighters
Protection against fire : Do not enter fire area without proper protective equipment,